

Baird

February 3, 2009

Ms. Teresa Rogers
Appalachian Power Co.
Hydro Generation
40 Franklin Road
Roanoke, Virginia 24011

Baird & Associates
2981 Yarmouth Greenway Drive
Madison, Wisconsin 53711 USA
T. 608 273 0592
F. 608 273 2010

oceans
engineering
lakes
design
rivers
science
watersheds
construction

Re: Claytor Lake Revised Shoreline Erosion Mapping

Dear Teresa,

Please find attached the amended shoreline characteristic mapping for Claytor Lake. Thank you for bringing the shoreline misclassification to our attention. We carefully reviewed all original data, including site photos and data logs. All data, analyses, and results – including tabular data and graphs are correct, as originally submitted. Additionally, the database used to determine the relative lengths of shoreline material types in November 2008 is correct and the values presented in the revised report are correct. This misclassification was due to the corruption of a file that occurred during the revision of the original maps and was limited to the shoreline maps that were revised in November. We apologize for any confusion or inconvenience this may have caused.

Please contact Mark Riedel or myself if you have any questions or would like to discuss further.

Sincerely,



Baird & Associates

Alex Brunton, Ph.D.
Associate

cc Mark Riedel; Mike Hreben

Enc: As Stated

11124.010